


## Area of Concern – Site: P11

Map Grid Location: E10 Site visit date/ team): 4/13/15/ BK, JZ Drainage Area (Sq. Mi.): 16.7  
 Name & Location: Corn Mill Shoals Trail at Little River Crossing



1. **Culvert (diameter/material/length):** \_\_\_\_\_
 

<input type="checkbox"/> clogged	<input type="checkbox"/> aquatic organism passage/ perched
<input type="checkbox"/> crushed	<input type="checkbox"/> erosion (upstream/ downstream)
<input type="checkbox"/> lack of natural bed	<input type="checkbox"/> piping
<input type="checkbox"/> safety hazard	<input type="checkbox"/> overtopping
  
2. **Trail/ Road Impact (trail/ road name):** Corn Mill Shoals Trail

<input type="checkbox"/> stormwater input	<input type="checkbox"/> sediment input
<input type="checkbox"/> bridge	<input type="checkbox"/> utilities
<input type="checkbox"/> unstable trail crossing	<input type="checkbox"/> erosion
<input checked="" type="checkbox"/> safety hazard	<input checked="" type="checkbox"/> human impact (hiking/biking)
<input checked="" type="checkbox"/> missing vegetation	<input checked="" type="checkbox"/> equine/ dog impacts
  
3. **Upland/ Stormwater**

<input type="checkbox"/> nonpoint source pollution	<input type="checkbox"/> upland erosion
<input type="checkbox"/> pollutant point source	<input type="checkbox"/> unvegetated upland area
  
4. **Lake/Pond/ Reservoir (reservoir name):** \_\_\_\_\_
 

<input type="checkbox"/> erosion	<input type="checkbox"/> lack of vegetation
<input type="checkbox"/> equine impact	<input type="checkbox"/> human impact (hiking/biking)
<input type="checkbox"/> safety hazard	<input type="checkbox"/> water quality (temperature, algae, geese, fecal)
  
5. **Other Problem Area(s)** (list contributing factors)

**Potential Solutions**

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> relocate trail/close trail/road | <input checked="" type="checkbox"/> trail/road crossing improvement |
| <input checked="" type="checkbox"/> vegetation/ shoreline planting  | <input type="checkbox"/> mechanical grading                         |
| <input type="checkbox"/> stormwater treatment                       | <input type="checkbox"/> animal watering                            |
| <input checked="" type="checkbox"/> human/ animal exclusion         | <input type="checkbox"/> culvert rehabilitation/ replacement        |
| <input type="checkbox"/> signs                                      | <input type="checkbox"/> culvert daylighting                        |
| <input type="checkbox"/> maintenance                                | <input type="checkbox"/> bridge replacement/improvement             |

**Comments**

Trail over widened and missing vegetation in vicinity of crossing. Actual crossing stable due to bedrock in riverbed.

