









Area of Concern – Site: P47

Map Grid Location: <u>J4</u> Site visit date/ team): <u>8/20/15/ JZ</u> Drainage Area (Sq. Mi.): < 0.1 Name & Location: <u>Tributary at Plantation Trail</u>	
Culvert (diameter/material/ □ clogged □ crushed □ lack of natural bed □ safety hazard	'length): 18" / CPP □ aquatic organism passage / perched ⊠ erosion (upstream / downstream) □ piping □ overtopping
2. Trail/ Road Impact (trail/ re □ stormwater input □ bridge □ unstable trail crossing □ safety hazard ☑ missing vegetation	oad name): Plantation Trail sediment input utilities erosion human impact (hiking/biking) equine/dog impacts
3. Upland/ Stormwater ☐ nonpoint source pollution ☐ pollutant point source	☐ upland erosion ☐ unvegetated upland area
 4. Lake/Pond/ Reservoir (reservoir) □ erosion □ equine impact □ safety hazard 5. Other Problem Area(s) (list of the content o	□ lack of vegetation □ human impact (hiking/biking) □ water quality (temperature, algae, geese, fecal)
Potential Solutions □ relocate trail/close trail/road ☑ vegetation/ shoreline planting □ stormwater treatment □ human/ animal exclusion □ signs □ maintenance	☐ trail/road crossing improvement ☐ mechanical grading ☐ animal watering ☐ culvert rehabilitation/ replacement ☐ culvert daylighting ☐ bridge replacement/improvement
Comments No problems with culvert. However,	trail in vicinity is over widened and lacking vegetation.

