Area of Concern – Site: P38

Map Grid Location: **H4** Site visit date/ team): 8/26/15/ JZ Drainage Area (Sq. Mi.): < 0.1

Name & Location: Tributary at Tarkiln Branch Road

1. **Culvert (diameter/material/length):** 16"/ CPP
   - ☐clogged
   - ☐crushed
   - ☐lack of natural bed
   - ☐safety hazard
   - ☐aquatic organism passage/ perched
   - ☐erosion (upstream/ downstream)
   - ☐piping
   - ☐overtopping
2. **Trail/ Road Impact (trail/ road name):** Tarkiln Branch Road
   - ☐stormwater input
   - ☐bridge
   - ☐unstable trail crossing
   - ☐safety hazard
   - ☒missing vegetation
   - ☐sediment input
   - ☐utilities
   - ☐erosion
   - ☐human impact (hiking/biking)
   - ☐equine/dog impacts
3. **Upland/ Stormwater**
   - ☐nonpoint source pollution
   - ☐pollutant point source
   - ☐upland erosion
   - ☐unvegetated upland area
4. **Lake/Pond/ Reservoir (reservoir name):**
   - ☐erosion
   - ☐equine impact
   - ☐safety hazard
   - ☐lack of vegetation
   - ☐human impact (hiking/biking)
   - ☐water quality (temperature, algae, geese, fecal)
5. **Other Problem Area(s)**(list contributing factors)

Potential Solutions

- ☐relocate trail/close trail/road
- ☒vegetation/ shoreline planting
- ☐stormwater treatment
- ☐human/ animal exclusion
- ☐signs
- ☐maintenance
- ☐trail/road crossing improvement
- ☐mechanical grading
- ☐animal watering
- ☐culvert rehabilitation/ replacement
- ☐culvert daylighting
- ☐bridge replacement/improvement

Comments

Culvert appears to be in good condition; however, bare areas exist in the vicinity.

Kee Mapping & Surveying